Approved For Release 2000/04/19 : CIA-RDP81B00879R000500080054-4

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11777

RECEIVED FROM PLANT 19

DATE RECD 4-4-57

P.O. NO.

VENDOR PACKING SLIP NO.

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.
322		141	D	12			

CHARGE TO: C/R ACCT. OR W.O. NO. P.O. NO.

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
24	731286 Gear Assembly Drive Idler	24		
	IPS #A002922			

RECEIVED BY HMC 106 | INSPECTED BY | DATE 4-4-57 | REJECTS RETURNED ON REQUISITION NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11778

RECEIVED FROM PLANT 19

DATE RECD 4-5-57

P.O. NO.

VENDOR PACKING SLIP NO.

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.
322		234	D	12			

CHARGE TO: C/R ACCT. OR W.O. NO. P.O. NO.

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
5	731697 Damper Unit	5		
	IPS #A002943			

RECEIVED BY HMC 106 | INSPECTED BY | DATE 4-5-57 | REJECTS RETURNED ON REQUISITION NO.

Approved For Release 2000/04/19 : CIA-RDP81B00879R000500080054-4